HEARTLAND ESTATES WORK ORDER STATUS REPORT

Date of Call/Email	Name	Address	Work Order Number	Nature of Call	Work Description	Status	Comments
2/12/2024	Jane Howe	213 Rayfield Circle	366	piece of siding disconnected due to wind	WO Submitted	Closed	repaired siding
1/29/2024	Kathy Johnson	219 Rayfield Circle	365	look at basement as it flooded	WO Submitted	Closed	inspctd inside &out - no wtr on flr - patio
6/23/2023	Joanne Wideman	105 McKay Drive	340	leak in guest bthrm - leak fxd but wtng on conf. from Joanne	WO Submitted	Pending	rf rprs made 8/22 - clng nds pnt
2/14/2023	Christine Fiordeliso	103 McKay Drive	N/A	bsement floor crckng & bsement walls damp & crckng	Dynamole looked at floors and walls	Pending	Dynamole nds to put in wphls
11/29/2022	Marylou Kime	200 Rayfield Circle	N/A	sdwlk nr frnt dr fllng apart-also look at sdwlk lip at 219/221	Mike inspctd and took pics of sidewalk	Pending	CAI and Domicello to quote
							2/23/2024